



MEDIA RELEASE

THICK LINE IS A NETTING SEAM, NOT CRACK ON MRT GUIDEWAY

Kuala Lumpur, 23 July 2015: MASS Rapid Transit Corporation Sdn Bhd (MRT Corp) wishes to respond to media queries following discussions on social media alleging that cracks have appeared on the MRT guideway over the Damansara Puchong Highway (LDP).

MRT Corp wishes to state that the thick line seen in pictures alleged to be a crack was in fact the joining for two pieces of netting covering the guideway over the LDP.

MRT Corp Director for Strategic Communications and Public Relations Encik Mahmood Abdul Razak said the netting was placed there as a precautionary measure as work was still being carried out on the guideway.

"The thick jagged line is actually the joining of two pieces of netting which were sewn together. It is not a crack on the concrete of the guideway which is being alleged in discussions in social media," he said.

Mahmood advised the public not to be unduly worried while driving beneath the guideway. Motorists should also not slow down to look when driving along the LDP at that location.

"I urge the public not to believe unsubstantiated claims being spread via social media on this matter," he said.

ENDS

For media enquiries, please contact:

Encik Leong Shen-Li
MRT Corp

012-3196602 / leong.shen-li@mymrt.com.my

Cik Amalina Ghazali
MRT Corp

016-2154055 / amalina.ghazali@mymrt.com.my